



NUMBER: 02-008-04

GROUP: Suspension

DATE: November 8, 2004

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Rattle Sound From Rear

OVERVIEW:

This bulletin involves replacing the rear shocks.

MODELS:

2005 (ZH) Crossfire SRT6 Coupe

NOTE: This bulletin applies to vehicles built on or before September 22, 2004 (MDH0922XX).

SYMPTOM/CONDITION:

The vehicle operator may describe a metallic rattle/clunking sound from the rear when going over bumps.

DIAGNOSIS:

If the sound is coming from either rear shock, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	05161528AB	Shock, Suspension - Right Rear
1	05174007AA	Shock, Suspension - Left Rear

REPAIR PROCEDURE:

1. Replace both rear shocks. Refer to the service information available in TechCONNECT. Refer to 2 - Suspension/Rear/Shock - Removal.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
02-15-15-90	Shock Absorber - Replace - Both Sides	1.3 Hrs.

FAILURE CODE:



67	Rattles
----	---------